


FIG. 1A



006000104300

Figure 1 B





Figure 1 C



03025 000 54366960

FIGURE 2A




FIGURE 2B




FIGURE 2C





FIGURE 2D



00000000000000000000

FIGURE 3A





FIGURE 3B



00000000000000000000

FIGURE 4A




FIGURE 4B




FIGURE 4C




FIGURE 5






FIG. 6A

Standard HP Hardware




Edge: 5 mm

FIG. 6B




center

FIG. 6C 8.6" Step on Upper Electrode



Edge: 5 mm


FIG. 6D



center

00250000000000000000000000000000

Figure 7



**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT OR DRAWING
- BLURRED OR ILLEGIBLE TEXT OR DRAWING
- SKEWED/SLANTED IMAGES
- COLOR OR BLACK AND WHITE PHOTOGRAPHS
- GRAY SCALE DOCUMENTS
- LINES OR MARKS ON ORIGINAL DOCUMENT
- REFERENCE (S) OR EXHIBIT (S) SUBMITTED ARE POOR QUALITY
- OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image problem Mailbox.